








SSR




VAS 455251-2026-04

XXX








Torx 20












ø2 mm








1






2





















6



7









www.dakstra.com/electricsupport

